
⚠ WARNING

If used incorrectly, there is a risk of death or serious injury.

Use correctly according to the "Safety Guide".



Safety Guide

Read before use X POWER

If you have any questions or notices when using it, please contact us.

CONTACT

SAN-EI SEIKO CO., LTD.

1000 KONO KAMONO-CHO

MINOKAMO, GIFU 505-0053 JAPAN

TEL:+81-574-25-3167

〈CONTACT FORM〉

IMPORTANT

- Give the Safety Guide to the operators who uses X POWER.
- Read the Safety Guide carefully before use.

SAN-EI SEIKO CO.,LTD.

IMPORTANT CONSIDERATIONS FOR SAFE USE

⚠ WARNING

If used incorrectly, there is a risk of death or serious injury.

REQUIRED	
Before you begin	❗ Read the instruction manuals and/or safety guide for grinding wheel and equipment. ❗ Use the appropriate X POWER that meets the specifications of the equipment and grinding wheel
Before operation	❗ Operator must wear appropriate protective equipment and clothing. ❗ Ensure the grinding wheel is free from damage or abnormalities. ❗ Confirm the X POWER is free from damage or deformity. ❗ Be careful of cuts caused by burrs when handling used X POWER.
Installation	❗ Make sure that the grinding wheel is completely stopped before installing and removing the X POWER. ❗ Clean the mounting parts of X POWER and the equipment to ensure that there is no rust inhibitor or foreign object adhesion before installation. ❗ Make sure to securely fastened after installing the X POWER. ❗ X POWER must be attached in the correct direction specified.
Operation	❗ Use the equipment after fully warmed up. ❗ Make sure the X POWER and the grinding wheel are not in contact before use. ❗ Supply grinding fluid properly. ❗ Make sure the cover/door of the equipment is securely closed before use. ❗ Be careful of cuts caused by burrs when handling X POWER.
Limit	❗ Confirm the thickness of X-part is at least 1mm from the base.
Storage	❗ Remove moisture and dirt, and store it after applying anti-rust treatment. ❗ Protect from damage or deformation. ❗ Must be stored in a place with lesser temperature variation. No direct sunlight.
Disposal	❗ Comply with the regulations when disposing grinding chips and fluids.

PROHIBITED	
Before you begin	⃠ Must receive special education on handling whetstone (Article 59, paragraph 3 of the Occupational Safety and Health Act). ⃠ Do not use for anything other than dress turning of ultra-abrasive grinding wheel. ⃠ Do NOT modify the X POWER.
Before operation	⃠ Grinding wheel must not be trued with a single stone diamond before use. (X POWER won't perform as originally expected) ⃠ Do NOT use X POWER if it is dropped or impacted. ⃠ Do NOT use if there is an abnormality such as a gap between X-part and the alloy part. ⃠ Do NOT use if scratch, nick, crack, and/or peeling is found in the X-part during pre-use inspection.
Installation	⃠ Do NOT use if a convex found on the mounting surface.
Operation	⃠ Do NOT use dry. ⃠ During truing and dressing, do NOT use with excessive cut amount.
Limit	⃠ Do NOT use if X-part thickness is less than 1mm from the base.
Storage	⃠ Do NOT soak in anti-rust oil and ethanol. ⃠ Do NOT store in the environment where acidic, alkaline atmospheres, or potentially causing chemical reactions such as peroxides. ⃠ Do NOT store in the areas where falling and impacting risk.

Post and/or keep the safety guide near the equipment and/or accessible location.